

FIGURES

- 1. 1955 AND 1975 USGS QUAD OF SITE**
- 2. 1999 AND 1998 USGS QUAD OF SITE**
- 3. 1997 AERIAL PHOTOGRAPH OF SITE**
- 4. 2004 AERIAL PHOTOGRAPH OF SITE**
- 5. PARCEL MAP OF SITE**



Section 16, T2S, R4E

From USGS Park City East and Park City West Quadrangles
(1955 and 1975) and GDT Dynamap (January 2000)

**TREASURE HILL SUBDIVISION PHASE 4
PARK CITY, UTAH**




Approximate Scale
1 inch = 2,000 feet

1051008



Approximate Site Location

Figure 1



Section 16, T2S, R4E

From USGS Park City East and Park City West Quadrangles
(1999 and 1998) and GDT Dynamap (January 2000)

**TREASURE HILL SUBDIVISION PHASE 4
PARK CITY, UTAH**



Approximate Scale
1 inch = 2,000 feet

1051008



1999 and 1998 USGS Quadrangle Maps

Figure 2



USGS Aerial Photograph
September 12, 1997



Approximate Scale
1 inch = 1,000 feet


**TREASURE HILL SUBDIVISION PHASE 4
PARK CITY, UTAH**

1051008



1997 Aerial Photograph of Site

Figure 3



© 2005 GlobeXplorer, Air Photo USA
 August 2004

TREASURE HILL SUBDIVISION PHASE 4

PARK CITY, UTAH



North

Approximate Scale

1" = 460'



EC.1

SHEET NO.

SCALE
NOT TO SCALE



SDI
614 Main Street, Suite 404
P.O. Box 4660, Park City, Utah 84060
435-649-4499

ELDRIDGE & NICHOLSON
ARCHITECTS
176 WEST 200 SOUTH
SUITE 300A
SALT LAKE CITY, UTAH 84101
(801) 363-4867 FAX: (801) 355-8888



EXISTING CONDITIONS
TREASURE HILL PHASE 4
Presented by: MPE INC.

P.O. Box 2429
Park City, UT 84060
(435) 649-7077
(435) 649-6215 Fax

REVISED
10-31-03
01-21-04

Figure 5