HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION		()	,
Name of Property:			
Address: 449 MAIN ST		AKA: 46	1 Main or 455 & 453 Main
City, County: Park City, Summit	County, Utah	Tax Num	ber: PC-156
Current Owner Name: 449 MAII	N LLC	Parent Pa	arcel(s):
Current Owner Address: PO BC			
Legal Description (include acrea	age): NORTH 1/2 LOT	14 BLK 10 PARK CITY	SURVEY , 0.02 AC
2 STATUS/USE			
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s)		Reconstruction Date: Permit #: □ Full □ Partial Historic Places: ☑ inelig	
3 DOCUMENTATION			
Blaes, Dina & Beatrice Lufkin. "Fina Carter, Thomas and Goss, Peter. University of Utah Graduate So Longstreth, Richard. <i>The Buildings</i> Alta Mira Press, a division of	□ abstract of □ tax card □ original bui □ sewer perr □ Sanborn M □ obituary ind □ city directo ey □ census red □ biographica □ newspaper bks, articles, interviews al Report." Park City Histo Utah's Historic Architecture chool of Architecture and a of Main Street; A Guide of Rowman & Littlefield Pun Street Historic District."	dilding permit mit laps dex ries/gazetteers cords all encyclopedias rs rs retc.) Attach copies of coric Building Inventory. Salt re, 1847-1940: a Guide. Sutah State Historical Socie to Commercial Architecture ublishers, Inc., 2000.	alt Lake City, Utah: ety, 1991. e. Updated edition. Walnut Creek, CA: ric Places Inventory, Nomination Form.
4 ARCHITECTURAL DESCRI	PTION & INTEGRITY		
Building Type and/or Style: 2-Pa	art Block		No. Stories: 2
Additions: □ none □ minor ☑	1 major (describe below)	Alterations: □ none □	minor
Number of associated outbuilding	ngs and/or structures: [☐ accessory building(s),	#; structure(s), #
General Condition of Exterior M	aterials:		

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

☑ Good (Well maintained with no serious problems apparent.)
☐ Fair (Some problems are apparent. Describe the problems.):
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
☐ Uninhabitable/Ruin
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Foundation: Tax cards indicate wood sills.
Walls: Wooden ship-lap siding.
Roof: Shed roof form.
Windows/Doors: Paired double-hung sash type in the upper façade and large display windows flanking central recessed entry doors with a ribbon of transom windows across the entire façade.
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:
Location: ☑ Original Location ☐ Moved (date) Original Location:
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The two-story frame 2-part block has been maintained, but changes made to the adjacent building replicate the historic building in such a way as to create a false sense of history. The alterations may seem compatible, but are conjectural and lack any authenticity. The changes are significant and diminish the site's original design integrity.
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The setting is typical of a mining era commercial core; buildings are located adjacent to one another and abut the sidewalk or street edge.
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines this as a typical Park City mining era commercial building are the simple methods of construction, the use of non-beveled (drop-novelty) wood siding, the recessed entrance and display windows, transom windows, the restrained ornamentation, and the plain finishes.
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of the commercial activity in a western mining town of the late nineteenth and early twentieth centuries. The building to the south was altered to make the subject building appear wider - the changes are completely conjectural.
Association (Describe the link between the important historic era or person and the property.): The two-part block is one of the most common commercial building types constructed in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.
This site was listed as a contributing building on the National Register of Historic Places in 1979 as part of the <i>Park City Main Street Historic District</i> . It was built within the historic period (1868-1929) and is associated with the mining era, but has subsequently had major alterations and would no longer be considered eligible for the National Register as part of an updated or amended nomination. As a result, it does not meet the criteria set forth in LMC Chapter 15-11 for designation as a Landmark Site. It, however, retains important local historic significance and meets the criteria set forth in LMC Chapter 15-11 for designation as a Significant Site.
5 SIGNIFICANCE
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1900
Builder: ☑ Not Known ☐ Known: (source:)

The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

	 					_		
1	н	ıc.	tr	r	^	Ε	ra	•
	 	ı.	u.	,, ,	١,	_	ıa	

☐ Settlement & Mining Boom Era (1868-1893)

☑ Mature Mining Era (1894-1930)

☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's commercial buildings represent the best remaining metal mining town business district in the state. The buildings along Main Street, in particular, provide important documentation of the commercial character of mining towns of that period, including the range of building materials, building types, and architectural styles. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining business district¹.

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation. Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 1995.

Photo No. 3: Southeast oblique. Camera facing northwest, tax photo.

Photo No. 4: Southeast oblique - with adjacent building (453 Main). Camera facing northwest, tax photo.

Park City Historical Society & Museum has an extensive library of historic photographs; time constraints did not permit review of available historic photographs for this report.

¹ From "Park City Main Street Historic District" written by Philip Notarianni, 1979 and "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

RE-APPRAISAL CARD Owner's Name Hernon, T. Owner's Address Park City Location N. - lot 14. Blk. 10 Survey Kind of Building Store noons over Street No. 461 .. Class..... Base Factor.. Stories Actual Factor Dimensions Cu. Ft. Sq. Ft. Totals No. of Rooms.. Condition. Add Deduct Ext. Walls Pot Roof-Type Flox Vacatsa Dormers-Small..... Med.... Bays-Small..... Med.... Porches—Front..... Rear.____@ Basement Floor Floor Attic-Rooms Fin. Heat-Stove H. A. Steam. Finish-Hd. Wd. Floors-Cabinets.. Tile-Walls. Lighting-Lamp..... Drops.... Fix Total Additions and Deductions.... Net Addition or Deductions.. REPRODUCTION VALUE. Owner Tenant Age Yrs. by Reproduction Val. Minus Dep. Remodeled..... Est. Cost.... .. Remodeling Inc... Garage-S 8-C.... Cars..... Walls... Roof...... Size.....x...... Age. Cost. Depreciated Value Garage. Remarks metal ail 1st a Total... Obsolescence 4 and 12 Total Building Value... Original Record.. Card No. Year By.


TITTITI III		()	
		Leanto	┦┤ ┼┼┼┼┼
╡┋┋			
<mark>·┼┈╎┈┼┈╎┈┼┈╎┈┼</mark> ┈┼			
- - - - - - - - - -			
+++++++++++++++++++++++++++++++++++++++	**		
	1/		++++++
	.0/	 ╄╇	
	24		
<u></u>	7		
<mark>╶</mark> ╇	┝ ┼┼┼┼┼┼		
			
<mark>- - - - - - - - - - - - - - - - - - - </mark>			
			
		.	
	┇┈┇┈┇┈┇ ╃┉╄┉╂┉╄		
	48		
usedap 5	4	- 1	
1 1 1 1 1 1 1 1 1		1000	
gami wa			
1227	2 aty		
	2 249		
	8		
	16.75°		┩ ╌┼┼┼┼┼
	Δ2/		
	07	┈┝┈┝┈┝┈┝┈┢┈┢╸	
	-7		
 			
I i i i i i i i i i i i i i i i i i i i			

OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Depr. Value
		X	1			
THE STATE OF THE S		X	7			
		Υ .	- '			
	1.37	v				
		x				
		۲				-
		x				
		X				
		X				
		x				-
		X				_
		x				_
		x	- 22			
		x		-		_
		x				
		x				-
	20-20-0	x				

Location	j .				1	Mary .		
	f Bldg. Stone	THE WORLD	St. No.	4611	Mai	~		- 13
Class	Rms.			Cost \$			x	_%
Stories	Dimensions	Cu.	Ht.	Sq. Ft.		Factor	Totals	
	x x	7 17 17		62.	5		\$ 2259	
2	x 12/2x 2	V		30		80	240	20
Lean	x x					1	The state of	
Att. G		lr.	Walls	1	Roof			
Att. O		of Buildin	g		Ad	ditions	upstans	
Founda	tion- Stone WD.			None			Vacant	TORY.
	Valls Sidiv							
	on— FloorsV		Clgs.				Joent	
Roof T	ype plat	Mtl.	1R	2	1100		wall	
	rs— Small1		Large				2 5 1005	
	Small Med		Large	200			25%	
	- Front			a		1000	0188	
	s — Front			ē		MILE		
	ent Entr.			<u>a</u>			-	
	ss			@			Bed Poo	m
	Bsmt. — 1/4 1/3 1/2 2/3	3/4 Full	_ Floor_	+		TO AND	up. us	ul
	AptRooms						-	
	Rooms Fin							
Attic	. Class 1	Tub	7	rays	W.			
	Basin	_Sink	T	oilet 1				
Plumbi	ing Urls.	_ Ftns		Shr.	+ .	360		
	Dishwasher_							
Heat-	Stove H.A.	Steam	_Stkr	Blr	H			
	Gas Coal	Fipel	ess	Kadiant	1	P. Hall		
	Cond			THE SAME	1			
	— Fir Ho				1		4 19 4	
	- Fir Hd.							
	ets Mante							
	WallsWai		Flo	ors	1			
	cal— Outlets		ixt.	C.1	1	To US		
Storm	Sash— Wood	Metal	_Doors	Sash				
Metal	Awnings	-		E VALUE OF				
***************************************		1		To Park May		936	THE STATES	
1		THE LAND				Tale 1		
-		THE PARTY				360		4
	Additions 1898		Parrol	uction Value			\$ 285	9
Year	Built 1898 A	vg.		Col. 1 2 3		309	76	
-	(Owner - Ten			/al. Minus l			85	7
Inf. h	Neighbor - R	ecord - Est.		or Rem.	-	259	1 1	4
_	del Year Est. C			ldg. Value			\$ 61	13
Garag	ge— Class	Depr. 2% 3	%		The same			
Cars_	Floor	Walls	1	Roof	_ Do	ors		
Size-	xA	ge	_ Cost _		,	·9	/c.	N. T
Other				T . 1 D . 1		Zalue.	s	
				Total Build	ing V	arue		
	aised Dec	6 -	19 3	Sy_	1	331	_	
Appr	a.s.tu					The state of		

*

Owners Name L.J. Hernon Location Lot 14 Bell 10 PC	
Location 14 Rele 10 FC	_
156 1/ ma / k	
Kind of Bldg. Tanung St. No. 485 No Main St	
Class / 5tore (3250) Type 1 @ 3 4. Cost \$ X	%
Stories Dimensions Sq. Ft. FactorTotalsTotal	s
2 x x 650 661 8 4297 8	
x x	_
x x	1
Att. Gar.—C.Px Fir Walls Cl	
Description of Buildings Additions Addition	is —
Foundation—Stone Conc Sills thank	_
Ext. Walls Siding	
Roof Type Flack Mtl. Bu	
Dormers—Small Med. Large	0
Bays—Small Med Large	
Porches—Front@	
Rear 1 8 x 2 4 Least 312 @ 100 312	
Porch @	
Planters @	
Ext. Base. Entry @	
Cellar-Bsmt. — 1/4 1/3 1/2 3/3 3/4 Full Floor	
	_
Bsmt. Gar.	
Basement-Apt Rms Fin. Rms.	_
Attic Rooms Fin. Unfin.	_
Class Tub Trays	
Plumbing Basin Sink Toilet Wtr. Sftr. Shr. St. O.T.	
Dishwasher Garbage Disp	_
Heat—Stove H.A. FA HW Stkr Elec.	
Oil Gas Coal Pipeless Radiant	
Air Cond. — Full Zone	
Finish—Fir. Hd. Wd. Panel	
Floor-Fir. Hd. Wd Other	
Cabinets Mantels.	
Tile -Walls Floors	
Storm Sash—Wood D. S. ; Metal D. S.	
Awnings — Metal Fiberglass	
Annings Model 11801g.ttss	
Total Additions 980	
	=
Year Built 18 98 Avg. 1. Replacement Cost 5277	-
Age 2. Obsolescence 25% 1519	_
Inf. by Owner - Tenant - Adj. Bld. Value 3958	-
Conv. Factor x.47	_
Replacement Cost—1940 Base	_
1970 " Depreciation Column 1 2 \$\mathbb{0}\)4 5 6	_
1940 Base Cost, Less Depreciation	
Total Value from reverse side	_
Total Building Value \$ DEC 1 0 1968	_
Appraised ① //-12 1968 By /333	
Appraised @	



RESIDENTIAL	OUT	BUILDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.		Depr. Value
				x				.47		
				x				.47		
				x				.47		
N				x				.47		
				x				.47		
	L			x				.47		
Cars	x	Age		_ Cost	-		x 47 %	ó		
					To	otal			, ,	
REMARKS	1 B	ed Room	rolle	e up	atoir	o ali	low	25%	all	

STATE OF UTAH - STATE TAX COMMISSION







