

HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION

Name of Property:

Address: 343 Park Ave

AKA:

City, County: Park City, Summit County, Utah

Tax Number: PC-44

Current Owner Name: NEELY BLAKE IV & BETH H/W (JT)

Parent Parcel(s):

Current Owner Address: 15720 WOODVALE RD, ENCINO, CA 91436

Legal Description (include acreage): ALL LOT 11 & S1/2 LOT 12 BLK 3 PARK CITY SURVEY; Acres 0.07

2 STATUS/USE

Property Category

- building(s), main
- building(s), attached
- building(s), detached
- building(s), public
- building(s), accessory
- structure(s)

Evaluation*

- Landmark Site
- Significant Site
- Not Historic

Reconstruction

- Date:
- Permit #:
- Full Partial

Use

- Original Use: Residential
- Current Use: Residential

*National Register of Historic Places: ineligible eligible
 listed (date: 7/12/1984 - Mining Boom Era Residences Thematic District)

3 DOCUMENTATION

Photos: Dates

- tax photo:
- prints:
- historic: c.

Drawings and Plans

- measured floor plans
- site sketch map
- Historic American Bldg. Survey
- original plans:
- other:

Research Sources (check all sources consulted, whether useful or not)

- abstract of title
- tax card
- original building permit
- sewer permit
- Sanborn Maps
- obituary index
- city directories/gazetteers
- census records
- biographical encyclopedias
- newspapers
- city/county histories
- personal interviews
- Utah Hist. Research Center
- USHS Preservation Files
- USHS Architects File
- LDS Family History Library
- Park City Hist. Soc/Museum
- university library(ies):
- other:

Bibliographical References (books, articles, interviews, etc.) Attach copies of all research notes and materials.

Blaes, Dina & Beatrice Lufkin. "Final Report." Park City Historic Building Inventory. Salt Lake City: 2007.

Carter, Thomas and Goss, Peter. *Utah's Historic Architecture, 1847-1940: a Guide*. Salt Lake City, Utah:

University of Utah Graduate School of Architecture and Utah State Historical Society, 1991.

McAlester, Virginia and Lee. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 1998.

Roberts, Allen. "Final Report." Park City Reconnaissance Level Survey. Salt Lake City: 1995.

Roper, Roger & Deborah Randall. "Residences of Mining Boom Era, Park City - Thematic Nomination." National Register of Historic Places Inventory, Nomination Form. 1984.

4 ARCHITECTURAL DESCRIPTION & INTEGRITY

Building Type and/or Style: Foursquare

No. Stories:

Additions: none minor major (describe below) Alterations: none minor major (describe below)

Number of associated outbuildings and/or structures: accessory building(s), # ____; structure(s), # __1__.

General Condition of Exterior Materials:

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

- Good (Well maintained with no serious problems apparent.)
 Fair (Some problems are apparent. Describe the problems.):
 Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
 Uninhabitable/Ruin

Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.):

Site: Stone retaining wall runs the length of frontage; line is broken to accommodate steps to entry porch.

Foundation: Tax cards indicate no foundation, not verified.

Walls: Drop siding.

Roof: Hipped roof form sheathed in asphalt shingles.

Windows/Doors: Paired double-hung sash type.

Essential Historical Form: Retains Does Not Retain, due to:

Location: Original Location Moved (date _____) Original Location:

Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including dates--known or estimated--when alterations were made): The one-story frame foursquare remain unchanged from the description provided in the National Register nomination form (see Structure/Ste Form, 1983).

Setting (The physical environment--natural or manmade--of a historic site. Describe the setting and how it has changed over time.): The setting remains unchanged from what is described in the National Register nomination form.

Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The physical evidence from the period that defines this as a typical Park City mining era house are the simple methods of construction, the use of non-beveled (drop-novelty) wood siding, the plan type, the simple roof form, the informal landscaping, the restrained ornamentation, and the plain finishes.

Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.

Association (Describe the link between the important historic era or person and the property.): The foursquare was a common house type built in Utah during the mining era.

This site was listed on the National Register of Historic Places in 1984 as part of the *Park City Mining Boom Era Residences Thematic District*. It was built within the historic period, defined as 1872 to 1929 in the district nomination, and retains its historic integrity. As a result, it meets the criteria set forth in LMC Chapter 15-11 for designation as a Landmark Site.

5 SIGNIFICANCE

Architect: Not Known Known: (source:) Date of Construction: c. 1898

Builder: Not Known Known: (source:)

The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:

1. Historic Era:

- Settlement & Mining Boom Era (1868-1893)
 Mature Mining Era (1894-1930)
 Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.¹

2. **Persons** (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):

3. **Architecture** (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation. Camera facing west, 2006.

Photo No. 2: East elevation. Camera facing west, 1995.

Photo No. 3: Northeast oblique. Camera facing southwest, 1983.

Photo No. 4: Southeast oblique. Camera facing northwest, tax photo.

¹ From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

SERIAL NO. RE-APPRAISAL CARD (1940 APPR. BASE)

Owner's Name _____
 Owner's Address _____
 Location _____
 Kind of Building Res Street No. 343 Park
 Schedule 1 Class 4 Type 1-2-3-4 Cost \$ _____ X _____ %

Stories	Dimensions	Cu. Ft.	Sq. Ft.	Actual Factor	Totals
<u>1</u>	x x		<u>844</u>	\$ -	\$ <u>2396</u>
	x x			\$	\$
	x x			\$	\$

No. of Rooms 4 Condition _____

Description of Building	Add	Deduct
Foundation—Stone <u>126 9/15</u> Conc. None <input checked="" type="checkbox"/>		<u>156</u>
Ext. Walls <u>Siding</u>		
Insulated—Floors _____ Walls _____ Clgs. _____		
Roof—Type <u>Hip</u> Mat. <u>Shg.</u>		
Dormers—Small _____ Med. _____ Lg. _____		
Bays—Small _____ Med. _____ Lg. _____		
Porches—Front <u>110" @ 1.10</u>	<u>121</u>	
Rear _____ @ _____		
Cellar—Basin't— $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ full-floor <u>No</u>		<u>45</u>
Basement Apts.—Rooms Fin. _____		
Attic Rooms _____ Fin. _____ Unfin. _____		
Plumbing— Class <u>1</u> Tub _____ Trays _____ Basin _____ Sink _____ Toilet _____ Urns _____ Ftns. _____ Shr. _____ Dishwasher _____ Garbage Disp. _____		
Heat—Stove <input checked="" type="checkbox"/> H. A. _____ Steam _____ S. _____ Blr. _____ Oil _____ Gas _____ Coal _____		
Air Conditioned _____ Incinerators _____		
Radiant—Pipeless _____		
Finish— Hd. Wd. _____ Floors— Fir. <input checked="" type="checkbox"/> _____ Hd. Wd. _____ Conc. _____		
Cabinets <u>1</u> Mantels _____		<u>125</u>
Tile— Walls _____ Wainscot. _____ Floors _____		
Lighting—Lamp _____ Drops <input checked="" type="checkbox"/> Fix. _____ <u>Wolbdinal Port W. S. 4 @ 30"</u>		<u>120</u>
Total Additions and Deductions	<u>121</u>	<u>446</u>
Net Additions or Deductions	<u>-121</u>	<u>2396</u>

Ave Age 45 Yrs. by Estl Owner
 Tenant
 Neighbors
 Records

REPRODUCTION VALUE \$ 2071
 Depr. 1-2-3-4-5-6 58/42 % \$ _____
 Reproduction Val. Minus Depr. \$ 870

Remodeled _____ Est. Cost _____ Remodeling Inc. _____ % \$ _____
 Garage—S 8 C _____ Depr. 2% 3% _____ Obsolescence _____ \$ _____
 Cars _____ Walls _____ Out Bldgs. _____ \$ _____
 Roof _____ Size x Age _____ \$ _____
 Floor _____ Cost _____ Depreciated Value Garage _____ \$ _____

Remarks (3) yrs Ave Used (1941) **Total Building Value** \$ _____

Appraised 10/1949 By CAO F A J

Serial No. PC44

Location _____
 Kind of Bldg. Rqd St. No. 343 Park
 Class 3 Type 1 2 3 4. Cost \$ _____ X _____ %

Stories	Dimensions	Cu. Ft.	Sq. Ft.	Factor	Totals
1	x x		844		\$ 1709
	x x				
	x x				

Gar.—Carport x Fr. _____ Walls _____ Cl. _____

Description of Buildings	Additions	
Foundation—Stone _____ Conc. _____ None <input checked="" type="checkbox"/>		
Ext. Walls <u>Siding</u>		
Insulation—Floors _____ Walls _____ Cigs. _____		
Roof Type <u>Shp</u> Mtl. <u>Shg</u>		
Dormers—Small _____ Med. _____ Large _____		
Bays—Small _____ Med. _____ Large _____		
Porches—Front <u>110</u> @ <u>1⁰⁰</u> <u>110</u>		
Rear _____ @ _____		
Porch _____ @ _____		
Metal Awnings _____ Mtl. Rail _____		
Basement Entr. _____ @ _____		
Planters _____ @ _____		
Cellar-Bsmt. — $\frac{1}{4}$ $\frac{1}{3}$ $\frac{1}{2}$ $\frac{3}{4}$ Full _____ Floor _____		
Bsmt. Apt. _____ Rooms Fin. _____ Unfin. _____		
Attic Rooms Fin. _____ Unfin. _____		
Plumbing {	350	
		Class <u>1</u> Tub <u>1</u> Trays _____
		Basin <u>1</u> Sink <u>1</u> Toilet <u>1</u>
		Wtr. Sfr. _____ Shr. St. _____ O.T. _____
Dishwasher _____ Garbage Disp. _____		
Built-in-Appliances _____		
Heat—Stove <input checked="" type="checkbox"/> H.A. _____ Steam _____ Stkr. _____ Blr. _____		
Oil _____ Gas _____ Coal _____ Pipeless _____ Radiant _____		
Air Cond. _____		
Finish—Fir <input checked="" type="checkbox"/> Hd. Wd. _____		
Floor—Fir <input checked="" type="checkbox"/> Hd. Wd. _____ Other _____		
Cabinets _____ Mantels _____		
Tile—Walls _____ Wainseot _____ Floors _____		
Storm Sash—Wood D. _____ S. _____; Metal D. _____ S. _____		
Total Additions	460	

Year Built _____	Avg. Age <u>53</u>	Current Value	\$ 2169
Inf. by { Owner - Tenant -	Neighbor - Record - Est.	Commission Adj.	%
Remodel Year _____		Est. Cost _____	Bldg. Value
Garage—Class _____	Depr. 2% 3%	Carport—Factor _____	
Cars _____	Floor _____	Walls _____	Roof _____
Size—x _____	Age _____	Cost _____	x _____ %
Other _____			
Total Building Value			\$

Appraised 12-3-59 By 1331

PC 44
Serial Number

OF
Card Number

Owners Name _____

Location _____

Kind of Bldg. Res St. No. 343 Park Ave

Class 3 Type 2 3 4. Cost \$ _____ X _____ %

Stories	Dimensions	Sq. Ft.	Factor	Totals	Totals
	x x	676		\$ 2970	\$
	x x				
	x x				

Att. Gar.—C.P. x Flr. _____ Walls _____ Cl. _____

Description of Buildings Additions Additions

Foundation—Stone _____ Conc. _____ Sills _____

Ext. Walls Sid (A)

Roof Type HIP Mtl. Pat + Alum

Dormers—Small _____ Med. _____ Large _____

Bays—Small _____ Med _____ Large _____

Porches—Front 110⁰ @ 120 132

Rear _____ @ _____

Porch _____ @ _____

Planters _____ @ _____

Ext. Base. Entry _____ @ _____

Cellar-Bsmt. — 1/4 1/2 1/2 3/4 Full None

Bsmt. Gar. _____

Basement-Apt. _____ Rms. _____ Fin. Rms. _____

Attic Rooms Fin. _____ Unfin. _____

Plumbing { Class 1 Tub. 1 Trays _____
Basin 1 Sink 1 Toilet 1 550
Wtr. Sfr. _____ Shr. St. _____ O.T. _____
Dishwasher _____ Garbage Disp. _____

Heat—Stove _____ H.A. _____ FA HW _____ Stkr _____ Elec. _____ 313

Oil _____ Gas Coal _____ Pipeless _____ Radiant _____

Air Cond. — Full _____ Zone _____

Finish—Fir. Hd. Wd. _____ Panel _____

Floor—Fir. Hd. Wd _____ Other _____

Cabinets 1 Mantels _____

Tile—Walls _____ Wainscot _____ Floors _____

Storm Sash—Wood D. _____ S. _____; Metal D. 1 S. _____ 30

Awnings — Metal _____ Fiberglass _____

108⁰ of STORAGE @ 1.50 252

Total Additions 1277

Year Built 1904 Avg. 1904 Replacement Cost 4247

Age 2. Obsolescence _____

Inf. by { Owner - Tenant -
Neighbor - Record - Est. } Adj. Bld. Value _____

Conv. Factor 118

Replacement Cost—1940 Base _____

Depreciation Column 1 2 3 4 5 6 _____


1940 Base Cost, Less Depreciation _____

Total Value from reverse side _____

Total Building Value \$ _____

Appraised ① 10-16 19 58 By 1701 DEC 13 1968

Appraised ② _____ 19 _____ By _____ 1328



SCALE:

RESIDENTIAL OUT BUILDINGS	Age	Size	Area	Fac-tor	Cost	Conv. Fac.	Adj. Cost	Depr. Value
		x				.47		
		x				.47		
		x				.47		
		x				.47		
		x				.47		
		x				.47		

Garage — Class _____ Depr. 2% 3% _____

Cars _____ Floor _____ Walls _____ Roof _____ Doors _____

Size _____ x _____ Age _____ Cost _____ x 47% _____

_____ 1940 Base Cost _____ x _____ % Depr. _____

Total _____

REMARKS _____



Structure/Site Information Form

IDENTIFICATION 1

Street Address: 343 Park Park City, Summit County, Utah UTM: 12 458120 4498980
 Name of Structure: House at 343 Park T. R. S.
 Present Owner: Robert W. Thielke
 Owner Address: 1026 Hillview Drive, Salt Lake City, Utah 84117
 Year Built (Tax Record): Effective Age: Tax #: PC 44
 Legal Description: Kind of Building:
 All Lot 11 and South half Lot 12 Block 3, Park City Survey
 Less than one acre.

STATUS/USE 2

Original Owner: probably Walter and Ann W. Wilcocks Construction Date: c. 1898 Demolition Date:
 Original Use: Residence Present Use:
 Building Condition: Integrity: Preliminary Evaluation: Final Register Status:
 Excellent Site Unaltered Significant Not of the National Landmark District
 Good Ruins Minor Alterations Contributory Historic Period National Register Multi-Resource
 Deteriorated Major Alterations Not Contributory State Register Thematic

DOCUMENTATION 3

Photography: Date of Slides: 1983 Slide No.: Date of Photographs: 1983 Photo No.:
 Views: Front Side Rear Other Views: Front Side Rear Other

Research Sources:
 Abstract of Title Sanborn Maps Newspapers U of U Library
 Plat Records/Map City Directories Utah State Historical Society BYU Library
 Tax Card & Photo Biographical Encyclopedias Personal Interviews USU Library
 Building Permit Obituary Index LDS Church Archives SLC Library
 Sewer Permit County & City Histories LDS Genealogical Society Other Census Records

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):
 1900 Census Records. Summit County, Park City Precinct. p. 156-A.
Deseret News. March 12, 1930, p. 10. Ann Wilcocks obituary.
Salt Lake Tribune. June 20, 1898, p.1.

Architect/Builder: unknown

Building Materials: wood

Building Type/Style: Pyramid House

Description of physical appearance & significant architectural features:
(Include additions, alterations, ancillary structures, and landscaping if applicable)

This house is a one story frame pyramid house with a truncated hip roof. Typical of the pyramid house is the square plan, the generally symmetrical facade with the door set slightly off center between pairs of double hung sash one over one light windows, the truncated hip roof, and the porch supported on lathe turned piers that spans the facade. The windows are framed with a common type of Victorian molding, one that is grooved and has decorative corner blocks. There is a rear shed extension on the northwest corner of the building, which in scale and materials complements the original section, and may in fact be original. In-period rear extensions are part of Park City's architectural vocabulary. Although in many cases an extension represents a major alteration of the original house, it usually contributes to the significance of a house because it documents the most common and acceptable method of expansion of the small Park City house. This house has received no major alterations and is in excellent condition. It maintains its original integrity.

Photos

Statement of Historical Significance:

Construction Date: c. 1898

Built c. 1898, the house at 343 Park is architecturally significant as one of 69 extant pyramid houses in Park City, 28 of which are included in this nomination. Of the 28 being nominated, 11 are true pyramid houses and 17 are variants of the basic type. This house is one of the true pyramid houses. The pyramid house is one of the three most common house types built during the early period of Park City's mining boom era, and significantly contributes to the character of the residential area. It appeared early on, but continued to be built with variations longer than the other two types.

This house was built by at least 1900, as indicated by the Sanborn Insurance Maps, having probably been built c. 1898 as investment property by Walter and Ann W. Wilcocks, who lived down the block at 363 Park. William Scoble, Ann Wilcocks' brother, sold them the property in 1888, at which time there was a different house located there. That house was probably destroyed in the fire of 1898, which burned many of the houses in town, including some along this the west side of Park Avenue.¹ Ann Wilcocks, widowed in 1900, probably rented out this house until selling it in 1905 to her 21 year old nephew, William J. Scoble (a son of William Scoble). The 1900 census records indicate that at that time this house was probably occupied by William Boyd, a druggist, and his family. William J. Scoble, who had previously lived with the Wilcocks in their neighboring house, owned this house until 1924, although it is unclear whether or not he ever lived here. Other owners of the house include Willard R. Jones (1924-26), Henry and Corina Tuggle (1926-49), and Robert W. Thielke (1949-c.1980).

¹Salt Lake Tribune, June 20, 1898, p. 1.



House at 343 Park
Park City, Summit County, Utah

View from Northeast corner

Photo by Roger Roper, October 1983
Negative: Utah State Historical Society





PARKING FOR
RESIDENTS OF
343 PARK AVE
ONLY