



RECLAIMED WOOD SIDING



RECLAIMED TIMBER POSTS



RECLAIMED WOOD SIDING

RECLAIMED TIMBER POST

HISTORIC PICTURES AND PLAQUES

BUILT UP GABLE ENTRY ROOF

IMPROVED STEEL GATE W/ STEEL MESH

STEEL STAND-OFF TEXT MOUNTED ON STEEL HEADER

RAIL CART

RECLAIMED TIMBER POST

RECLAIMED WOOD SIDING

LANDSCAPING BOULDERS


SPIRO MINE ENTRY CONCEPT



ENLARGED VIEW OF ENTRY



GROUND LEVEL VIEW OF ENTRY



AERIEL VIEW OF ENTRY



PLAN VIEW